

CORNER RECORD


Agency Index BK 23, PG 53
 Document Number 20210012

City of Rocklin County of _____ Placer _____, California
 Brief Legal Description Center rad. point Pecan Court, Antelope Oaks Unit No. 2, Bk. N of Maps, Pg. 40

Sec. 18

CORNER TYPE

COORDINATES (Optional)



- ☐ Government Corner ☒ Control
☐ Meander ☐ Property
☐ Rancho ☐ Other

N. _____ E. _____
 Elevation _____
 Units ☐ Metric ☐ U.S. Survey Foot
 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____
☐ Complies with Public Resources Code §§8801-8819
☐ Complies with Public Resources Code §§8890-8902

Date of Survey November 5, 2020

T. 11 N., R. 7 E., M.D. B. & M.

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:
 Corner/Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☐ Pre-Construction
☐ Found and tagged ☒ Reestablished ☐ Referenced ☒ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Replaced original found monument per C.R. 23/43 on 11/05/2020 with countersunk survey spike and washer stamped LS 5914 based upon the ties established per C.R. 23/43 after the original monument was destroyed as a result of construction.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on February 5, 2021

Signed [Signature] P.L.S. or R.C.E. No. 5914



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 22, 2021

and examined and filed FEBRUARY 26, 2021

Signed [Signature] P.L.S. or R.C.E. No. 8373

Title Deputy Co. Surveyor

County Surveyor's Comment




BOOK 23 OF CORNER RECORDS PAGE 53



N MAPS 40

SET SURVEY SPIKE AND
WASHER STAMPED LS 5914

68



66

67